

Lighting Audit Fixture Report

LighTec, Inc.

Reference

;

Prepared By: Richard Ellis

Version: 1.0

Reference Lighting Audit Fixture Report 8/18/2009

Zone	Location	Existing Condition	Action	Proposed Condition	EQty	PQty	Accessories
typical							
1	Front Office Area Common	65R30 Inc. Recessed Can	Lamp Replacement	Retro 16W CFL Par 30 Flood	12	16	No accessories
1	Front Office Area Common	4L 34W-T12 Troffer EE/Std Mag	Remove & Install Recessed Fixture	NF 2x4 3L 30W Prismatic Troff HP T8 BF L	24	24	No accessories
1	Front Office Area Offices	4L 34W-T12 Troffer EE/Std Mag	Relamp, Reballast, & Clean	Retro 4L 32W 841 HP T8 BF L	12	12	No accessories
2	Warehouse	No New System Required	Install Fixture Mounted Sensor	Fixture Installed Sensor	0	20	0
2	Warehouse	400W Metal Halide Highbay	New T5 Installation	NF 2X4 4 Lamp T5 OFO w/Slvr Refl & Cord	1	1	No accessories
4	Manufacturing	1x8 2L Ind HO Shaded EE/StdMag	1x8 Kit	Kit-1x8 2L Tand 32W HP T8 w/ Wht Refl BF L	48	48	No accessories
5	Inspection Stations	1x4 2L 34W T12 Wrap EE/EEMag	Relamp, Reballast, & Clean	Retro 2L 30W 841 HP T8 BF L	24	12	No accessories
6	Shipping & Receiving	1x8 2L Ind HO Shaded EE/StdMag	1x8 Kit	Kit 1X8 2LTand 30W 841 w/ Wht Refl HP T8 BF L	12	12	No accessories
7	Shipping Office	2x4 4L 34W T12 EE/EEMag Troff	Relamp, Reballast, & Clean	Retro 2L 32W HP T8 BF H	2	2	No accessories

typical

135

147

Zone	Location	Existing Condition	Action	Proposed Condition	EQty	PQty	Accessories
Grand Total:					135	147	
